

# PLANNING CHECKLIST:

## Five Key Steps for 2D to 3D Transition Planning

### About this checklist:

Transitioning from 2D to 3D design requires thorough preparation and a structured process. This categorized checklist outlines essential tasks and considerations to ensure a smooth transition, with definitions of how each supports the planning phase and long-term success.

[Contact KETIV](#) if you have questions or need guidance on your 2D to 3D design transition.

### 1. Program Management and Leadership Alignment

- Assign a Program Manager  
A dedicated manager will oversee timelines, resources, and stakeholder alignment.
- Identify Champions & Power Users  
Appoint experienced users to lead adoption efforts and mentor others.
- Set Training Goals  
Define the training strategy to ensure all team members will be able to gain proficiency with the new tools.
- Set Training Goals  
Define the training strategy to ensure all team members will be able to gain proficiency with the new tools.

### 2. Industry Research and Goal Setting

- Research Industry Trends  
Study how similar companies are leveraging 3D workflows to determine best-practices.
- Focus on Proven Methodologies  
Adopt practices validated in similar industries to avoid common pitfalls.
- Identify Milestones  
Set clear objectives to track the progress of your 3D adoption (e.g., first automated BOM release, first full 3D assembly).
- Measure Success  
Define metrics for success, such as time savings, error reduction, or improved collaboration between teams.

### 3. Workflow Assessment and Cross-Functional Collaboration

- Assess Existing Workflows and Dependencies  
Map current workflows across departments to identify manual steps or inefficiencies that can be automated.
- Engage Cross-Functional Teams  
Ensure all relevant departments—engineering, operations, manufacturing, and sales—are involved in designing new processes. (Example: Align with sales on how BOMs will integrate into their order management systems.)
- Capture Design Standards and Templates  
Document current design conventions, part naming schemes, and templates to maintain consistency across new 3D workflows.

### 4. Licensing, Documentation, and Reference Building

- Anticipate Licensing Needs and Budget  
Evaluate Autodesk tool licenses (e.g., Inventor, Vault, Plant 3D) and budget for future scaling.
- Maintain Good Documentation  
Develop comprehensive documentation for new workflows, licensing processes, and troubleshooting guides.
- Build a Database of Reference Materials  
Create a library of whitepapers, tutorials, and internal videos to support ongoing learning. (Example: Use Autodesk KVA recordings and unlisted YouTube tutorials to build this knowledge base.)

### 5. Long-Term Adoption and Change Management

- Identify Impacts to Product Development and Customer Lifecycle  
Evaluate how the transition will affect delivery timelines, customer expectations, and post-sale service processes. (Example: If manufacturing relies on 2D PDFs, ensure the new 3D process provides automated PDF exports through Vault.)
- Anticipate Team Size and Structure Needs  
Set clear objectives to track the progress of your 3D adoption (e.g., first automated BOM release, first full 3D assembly).
- Plan for Recurring Engagement  
Schedule monthly check-ins or team meetings to monitor the transition and identify areas for improvement.